

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DX619
WSW
1/2-1
0.917 mi.
4843 ft.

INTERSECTION 129TH ST AND MERMAID
INTERSECTION 129TH ST AND MERMAID
BROOKLYN, NY

NY Spills **S110044073**
N/A

Site 5 of 5 in cluster DX

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: INTERSECTION 129TH ST AND MERMAID
Address: INTERSECTION 129TH ST AND MERMAID
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0907964 / 2009-11-30
Facility ID: 0907964
Facility Type: ER
DER Facility ID: 369561
Site ID: 420534
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2009-10-15
Investigator: Con Ed Unassigned
Referred To: Not reported
Reported to Dept: 2009-10-15
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2009-10-15
Spill Record Last Update: 2009-11-30
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT
DEC Memo: "11/30/09 - See eDocs for Con Ed report detailing cleanup and closure. 1 gal of oil on 200 gal of water."
Remarks: "unknown material on water. Sump involved. Clean up pending. ref # 218 829"

All Materials:

Site ID: 420534
Operable Unit ID: 1176487
Operable Unit: 01
Material ID: 2169178
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: Not reported
Oxygenate: Not reported